



50' Frame Summary Table	
Out to Out Dimension	50'-0"
Overall Height	20'-0 3/8"
Up and Over Measurement	69'-0 1/2"
Truss Depth Center to Center	1'-7 1/2"
Chord Size	1.9" x 14 gage
Web Size	1" x 16 gage
Purlin Size	1.9" x 14 gage
Cable Bracing Size	3/16"
Connector Plate Dimensions	2" x 1'-9 1/8" x 1/2"
Filler Plate Dimensions	2" x 1'-6 3/4" x 1/4"
Cable Brace Connector Angle	2" x 2" x 1/4" x 2"